


600A



Box List

Item No: 600A		Worker	Q C	ganger
Box				
Part name	Quantity			
Front wire(前网)	1pcs			
Back wire(后网)	1pcs			
Left wire(左网)	1pcs			
Right wire(右网)	1pcs			
Plastic bottom(600A胶盆)	1pcs			
Assembly Instructions(包装图)	1pcs			
Bottom perch(下棍)	1pcs			
Grill(密网)	1pcs			
Bottom grill(脚网)	1pcs			
Top wire(盖网)	2pcs			
Supporting grill(稀网)	1pcs			
Bottom frame(脚框)	1pcs			
Hosre (脚架)	4pcs			
Feeders(4寸杯)	2pcs			
Wheels(2寸8厘脚轮)	4pcs			
Screw bag(螺丝包)	1pcs			

1. Screw 4x wheels onto bottom of the 4x legs ;
2. Attach 4x legs and leg frame together with screws to form a stand;
3. Put front, back, left, right wire mesh together to form body.
4. Slide grill, supporting grill and plastic bottom into bottom of the cage;
5. Put top wire mesh inside the body on the 4 hitches at bottom.
6. Put 2x feeder cups inside the feeder doors.
7. Put the perch from left to right inside body.
8. Assembly top wire meshes on top of body.
9. Put the body on the stand from a cage.