


OCT5252

Box List



Item No: OCT5252				
Box 1/3		Worker	Q C	ganger
Part name	Quantity			
Side wire (No leg) (侧网/无脚)	4pcs			
Assembly Instructions (包装图)	1pcs			
Box 2/3		Worker	Q C	ganger
Side wire (With legs) (侧网/有脚)	4Pcs			
Box 3/3		Worker	Q C	ganger
Tray (铁盆)	3pcs			
Top wire (盖网)	2pcs			
Grill (密网)	3pcs			
Holder (5寸合圈)	4pcs			
Feeders (5寸杯)	4pcs			
Perch (木棍)	2pcs			
Wheels (3寸12厘脚轮)	8pcs			
Tray guide (拉盆槽)	2pcs			
Screw bag (螺丝包)	1pcs			

1. Screw 6 x wheels onto bottom of side wire ;
2. Attached side wire together to form body;
3. Screw top wire on the top of body;
4. Screw tray guide into the inner cage;
5. Screw holders into the inner cage;
6. Slide grills into the cage;
7. Slide trays into the cage;
8. Put the perches into the cages;
9. Put the cups into the dish holder;