


R Y 3 2 2 3

Box List



Item No: RY3223				
Box 1/2		Worker	Q C	ganger
Part name	Quantity			
Front wire(前网)	1pcs			
Back wire(后网)	1pcs			
Left wire(左网)	1pcs			
Right wire(右网)	1pcs			
Seed guards(裙边)	4pcs			
Grill(密网)	1pcs			
Assembly Instructions(包装图)	1pcs			
Bottom perch(下棍)	1pcs			
Box 2/2		Worker	Q C	ganger
Top wire(盖网)	2pcs			
Bottom panel(脚板)	1pcs			
Tray (铁盆)	1pcs			
Wheels(2寸8厘脚轮)	4pcs			
Feeders(5寸杯)	3pcs			
Holder(5寸合圈)	3pcs			
Screw bag(螺丝包)	1pcs			

1. Screw 2 x wheels onto bottom of front wire then 2 x wheels onto bottom of back wire.
2. Attach front、back、left、right wire together with M5X25 screws.
3. Assembly top wire (2x top wire meshes) on top of the body with M5X25 screws.
4. Assembly bottom wire at the bottom of the body with M5X25 screws.
5. Slide grill in space underneath the front door.
6. Put 4 x seed guards in place above bar around the body.
7. Slide tray in space underneath front seed guard .
8. Screw 3 x door feeders on inside of 3 x doors.
9. Open the front door and put perch from left to right inside the body.